

TopsWorks 2021 SP2 | What's new

Release: October 2021

This release includes several improvements and bug fixes:

DPS- SPR #	Type	Description
2644	BUG	Command manager displays tabs without names
2648	BUG	Support for thread display as a sub-feature of chamfers possible from SOLIDWORKS 2022 (TopsWorks 2021 is not compatible with SOLIDWORKS 2022)

FR = Feature Request