

## TopsWorks 2024 SP0 | What's new

Release: April 2024

This release includes several improvements and bug fixes:

DPS- SPR #	Type	Description
		SOLIDWORKS 2024 support
		Support of TruTops Boost V16 (with TBS module installed and licensed)
2692	BUG	GEO is not opened if it contains text elements that reference bend attributes
2693	BUG	GeoExport crash with fixed area with library feature and "Link to library part" option
2697	BUG	Sheet metal feature in multibody sheet metal part disappears when rebuilding before inserting bend parameters (SOLIDWORKS 2023 SP4)
2702	BUG	Blocked raw materials from Boost are not taken into account
2713	BUG	UpdateBendParameter API: No warnings are issued, although bends have warnings
2722	BUG	Unplausible TruTops Boost data intercepted
2592	FR	Raw material should be written to the GEO

FR = Feature Request